

School Building Authority of West Virginia
GRANT COUNTY NEEDS PROJECT – COUNTYWIDE ENERGY MANAGEMENT PLAN



The existing boilers are fifty years old and have outlived their life expectancy.



The existing roof has low spots and allows standing water. Leaks are found throughout the facility causing damage ceiling tile.



The existing water treatment plant is over forty years old and multiple leaks due to rusting equipment.



The existing lighting is outdated and inefficient. Ceilings are old and damaged from leaks in the roof.