School Building Authority of West Virginia MINERAL COUNTY – NEW ROOFING AND HVAC REPLACEMENT AT KEYSER AND FRANKFORT MS



Overview of the Frankfort Middle School facility and roofing area.



Bus loop/ parent drop of area and front entry view of Keyser Middle School



Typical roof area at Frankfort MS showing shingles that are failing in many locations around the facility.



Typical roof top unit and example of ponding water on the roof of Keyser Middle School