

School Building Authority of West Virginia
SUMMERS COUNTY – ROOF REPLACEMENT AT SUMMERS COUNTY MS



Street view of Summers County MS showing mold stains from moisture issues both above and below the windows. This is typical throughout the facility.



Roof leaks are common throughout the facility and cause regular disruptions to the students during rain events.



Example of the extensive patching and repairs performed to the EPDM roofing by the county maintenance staff in an attempt to slow roofing leaks.



Ponding water and failing wall flashings in the Thermoplastic roofing. This area can not be patched due to the type of roofing membrane used.