

School Building Authority of West Virginia
BARBOUR COUNTY- PHILIPPI ELEMENTARY ROOF REPLACEMENT



Large patches on roof to fix leaks.



Frayed edge of EPDM at roof's edge where water is running down into building.



Damaged tile in classroom where maintenance personnel are tracking gutter and downspout failure.



Classes moved to the next room while the room dries out.