

School Building Authority of West Virginia
MONROE COUNTY - JAMES MONROE HIGH SCHOOL - ROOF REPLACEMENT



Leaks staining the ceiling tile is a common occurrence throughout the facility.



Maintenance staff must remove gravel to find leaks.



In certain areas the insulation and deck have sunk, and water does not drain correctly.



Bridging has occurred here, which is when the membrane no longer adheres to the parapet and pulls away from the wall.