

JEFFERSON COUNTY – NEW RANSON AND SHEPHERDSTOWN ELEMENTARY SCHOOLS



Traffic circulation and parking at the existing Ranson Elementary is limited and unsecure.



The cafeteria at Ranson Elementary has been cited for not having fire-rated separation at the openings to kitchen.



The portables/ annex buildings at Ranson Elementary School are cited by the state Fire Marshal for failing fire alarm testing.



Site of the purchased property along WV Route 9 with signs posted for the future Ranson Elementary school.


JEFFERSON COUNTY – NEW RANSON AND SHEPHERDSTOWN ELEMENTARY SCHOOLS




Shepherdstown Elementary School's entrance is located away from the main office.



The kitchen is undersized, and the office is a small room carved out of the cafeteria due to lack of space.



Due to limited break-out space within SES, students and teachers must work in the main corridor.



Site of the future Shepherdstown Elementary School.