

MINERAL COUNTY – KEYSER HIGH SCHOOL - PARTIAL HVAC AND ROOF REPLACEMENT



Scope includes replacement of two DOAS units serving most of the classroom and removal of the Ballast (gravel) roof.



The rooftop unit serving the main office and entry area will be replaced.



The humidity issue at the school are creating mold problems that is damaging stored items.



The lack of ductwork for return air creates more dust/dirt particulates, since air gets pulled into ceiling cavity.