

GILMER COUNTY NEEDS PROJECT – GILMER COUNTY HIGH SCHOOL – PHASE III HVAC RENOVATION



The existing roof top units do not provide adequate air exchange.



Image of a roof top unit to be replaced over the locker rooms.



This is a roof top unit to be replaced over the weight room.



The commons area and overflow dining area lacks proper ventilation.