

School Building Authority of West Virginia
BRAXTON COUNTY- HVAC REPLACEMENT AT BRAXTON COUNTY MIDDLE SCHOOL



Rooftop HVAC unit that serves the gymnasium in need of replacement.



The HVAC units are original to the building, are located above the ceiling, and need constant repairs.



Outdated boilers that serve the building. Only one is currently operational.



Split system HVAC unit to be replaced.