

School Building Authority of West Virginia
HAMPSHIRE COUNTY – HAMPSHIRE HIGH SCHOOL – PARTIAL ROOF REPLACEMENT



Highlighted area represents partial roof replacement at Hampshire High School.



Fasteners are punching through roof from underneath.



Seams are failing since they do not have sufficient overlay.



A new roof over the gym will prevent water penetration from damaging the floor.