

PENDLETON COUNTY- HVAC REPLACEMENT AT BRANDYWINE ES AND ROOF REPLACEMENT AT PCMHHS



Aging rooftop units (RTU) at Brandywine Elementary, situated upon an EPDM roofing membrane in need of replacement.



Mini-split system HVAC units at Brandywine ES that are approaching the end of their useful life.



The metal roofing over Pendleton County Middle/High School has been patched in numerous places, with leaks throughout the building.



The worst areas of water infiltration in the building are located where the metal roofing transitions to other roofing sections. These areas would also be addressed.