

School Building Authority of West Virginia
RANDOLPH COUNTY – ELKINS MIDDLE SCHOOL – ROOF REPLACEMENT



The roof where seams have been patched and reglued.



The area of school where sprayed insulation was placed.



The corridor where leaks continue to occur.



Current access to the roof is on a chair then out a window.
Access door to be operational and new ladders on roof.