

# GILMER COUNTY - GILMER COUNTY MS/HS WALK-IN COOLER/FREEZER REPLACEMENT



Gilmer County MS/HS was built in 1958 and has had minor renovations since.



The freezer door get stuck because the concrete slab is failing outside.



The cooks have to go outside to access the refrigerator and dry storage area.



The new site is located beside the kitchen and cooks will not have to go outside to gain access.